

The following price schedule is in US\$ covers calibration (with adjustment if needed) and repair & calibration for units which need repair. The repair & calibration prices shown cover most repairs, additional charges may apply for units with physical damage or in cases where major assemblies need to be replaced entirely. A \$100 minimum evaluation fee may apply for units beyond economic repair.

Calibration & Repair Price Schedule

Vitretek Model	Calibration Only		Repair & Calibration	
	NIST Cal with No Data	ISO 17025 Accredited Cal with Data &	NIST Cal with No Data	ISO 17025 Accredited Cal with Data & Uncertainties
V7X Series Hipot Testers				
V70	\$132.00	\$236.00	\$656.00	\$761.00
V71	\$153.00	\$257.00	\$709.00	\$814.00
V73	\$184.00	\$289.00	\$761.00	\$866.00
V74	\$215.00	\$320.00	\$834.00	\$940.00
V75	\$215.00	\$320.00	\$834.00	\$940.00
V76	\$215.00	\$320.00	\$834.00	\$940.00
V79	\$131.00	\$236.00	\$656.00	\$761.00
95X Series Hipot Testers				
951i	\$341.00	\$499.00	\$887.00	\$1,045.00
952i	\$362.00	\$520.00	\$940.00	\$1,097.00
953i	\$362.00	\$520.00	\$940.00	\$1,097.00
954i	\$394.00	\$551.00	\$971.00	\$1,129.00
955i	\$415.00	\$572.00	\$992.00	\$1,150.00
957i	\$436.00	\$593.00	\$1,013.00	\$1,171.00
959i	\$310.00	\$415.00	\$782.00	\$940.00
AC30	\$100.00	\$205.00	\$761.00	\$866.00
4700 Precision HV Meters				
4700	\$520.00	\$835.00	\$940.00	\$1,255.00
HVL/P-35	\$205.00	\$310.00	\$520.00	\$625.00
HVL-70	\$310.00	\$415.00	\$625.00	\$730.00
HVL-100	\$362.00	\$467.00	\$730.00	\$835.00
HVL-150	\$415.00	\$520.00	\$835.00	\$940.00
PA900 Power Analyzers				
PA900 Mainframe			repair only \$625	repair only \$625
Channel Card	\$100.00	\$152.00	\$415.00	\$467.00
Discontinued Products				
V60/V50	\$236.00	\$341.00	\$887.00	\$992.00
V61/V51	\$257.00	\$362.00	\$940.00	\$1,045.00
V63/V53	\$289.00	\$394.00	\$971.00	\$1,076.00
V4	\$320.00	\$425.00	\$992.00	\$1,097.00
944i	\$394.00	\$499.00	\$940.00	\$1,045.00
944i/DC10	\$499.00	\$604.00	\$1,045.00	\$1,150.00
944i/LVIR	\$499.00	\$604.00	\$1,045.00	\$1,150.00

2019 Global Price List

Prices Effective September 1, 2019, USD
Vitretek Calibration & Repair

Terms: NET 30, FOB Poway
Freight Charge Additional

930i	\$362.00	\$467.00	\$908.00	\$1,013.25
4600A	\$520.00	\$835.00	\$835.00	\$1,150.00
4620A	\$520.00	\$835.00	\$835.00	\$1,150.00
4640A	\$572.00	\$887.00	\$887.00	\$1,202.00
4670A	\$604.00	\$919.00	\$919.00	\$1,234.00

The above rates are for service at the Vitrek factory in San Diego, CA USA and do not include shipping charges.

***** Cal stuff not part of price schedule *****

Calibration & Repair

Vitretek's Calibration Quality Control System is accredited to ISO 17025 by A2LA so you can be certain that you are receiving the highest quality instrument calibration available. Vitrek is pleased to provide world class customer support - before, during and after the sale. Our highly skilled factory service technicians take pride in getting the job done right and providing standard cal/repair turnaround times that are among the fastest in the test equipment industry.

Need Factory Service?

To arrange to have your unit factory serviced, email info@vitrek.com to request a RMA number. Please include model number, serial number, type of service requested and a description of the problem if repair is needed.

To locate an international service center, visit "Sales Network" on www.vitretek.com or email info@vitrek.com and request the location of the nearest service center.