

2022 Global Price List

Prices Effective April 1, 2022, USD
Vitretek Calibration & Repair

Terms: NET 30, FOB Poway
Freight Charge Additional

The following price schedule is in US\$ covers calibration (with adjustment if needed) and repair & calibration for units which need repair. The repair & calibration prices shown cover most repairs, additional charges may apply for units with physical damage or in cases where major assemblies need to be replaced entirely. A \$100 minimum evaluation fee may apply for units beyond economic repair.

Calibration & Repair Price Schedule

Vitretek Model	Calibration Only		Repair & Calibration	
	NIST Cal with No Data	ISO 17025 Accredited Cal with Data &	NIST Cal with No Data	ISO 17025 Accredited Cal with Data & Uncertainties
V7X Series Hipot Testers				
V70	\$155	\$278	\$772	\$896
V71	\$180	\$302	\$834	\$958
V73	\$217	\$340	\$896	\$1,109
V74	\$253	\$377	\$982	\$1,106
V75	\$253	\$377	\$982	\$1,106
V76	\$253	\$377	\$982	\$1,106
V79	\$154	\$278	\$772	\$896
95X Series Hipot Testers				
951i	\$401	\$587	\$1,044	\$1,230
952i	\$426	\$612	\$1,106	\$1,291
953i	\$426	\$612	\$1,106	\$1,291
954i	\$464	\$649	\$1,143	\$1,329
955i	\$488	\$673	\$1,168	\$1,353
957i	\$513	\$698	\$1,192	\$1,379
959i	\$365	\$488	\$920	\$1,106
AC30	\$118	\$241	\$896	\$1,020
4700 Precision HV Meters				
4700	\$612	\$983	\$1,106	\$1,477
HVL/P-35	\$241	\$365	\$612	\$736
HVL-70	\$365	\$488	\$736	\$860
HVL-100	\$426	\$550	\$859	\$983
HVL-150	\$489	\$612	\$983	\$1,106
PA900 Power Analyzers				
PA900 Mainframe			repair only \$736	repair only \$736
Channel Card	\$118	\$179	\$488	\$550
98x Series Teraohmmeter/IR Tester				
981	\$488	\$673	\$1,168	\$1,353
983	\$488	\$673	\$1,168	\$1,353



(858) 689-2755

www.Vitretek.com • Info@Vitretek.com

2022 Global Price List

Prices Effective April 1, 2022, USD

Vitretek Calibration & Repair

Terms: NET 30, FOB Poway
Freight Charge Additional

DL Electronic DC Load				
DL115	\$166	\$231	\$696	\$760
DL150	\$166	\$231	\$696	\$760
DL215	\$187	\$251	\$722	\$786
DL250	\$187	\$251	\$722	\$786
DL515	\$209	\$273	\$765	\$808
DL550	\$209	\$273	\$765	\$808

Discontinued Products				
V60/V50	\$278	\$401	\$1,044	\$1,168
V61/V51	\$303	\$426	\$1,106	\$1,230
V63/V53	\$340	\$464	\$1,143	\$1,266
V4	\$377	\$500	\$1,168	\$1,291
944i	\$464	\$587	\$1,106	\$1,230
944i/DC10	\$587	\$711	\$1,230	\$1,354
944i/LVIR	\$587	\$711	\$1,230	\$1,354
930i	\$426	\$550	\$1,069	\$1,193
4600A	\$612	\$983	\$982	\$1,354
4620A	\$612	\$983	\$982	\$1,354
4640A	\$374	\$1,044	\$1,044	\$1,415
4670A	\$711	\$1,082	\$1,082	\$1,452

The above rates are for service at the Vitrek factory in San Diego, CA USA and do not include shipping charges.

Calibration & Repair

Vitretek's Calibration Quality Control System is accredited to ISO 17025 by A2LA so you can be certain that you are receiving the highest quality instrument calibration available. Vitrek is pleased to provide world class customer

Need Factory Service?

To arrange to have your unit factory serviced, email info@vitrek.com to request a RMA number. Please include

To locate an international service center, visit "Sales Network" on www.vitretek.com or email info@vitrek.com and